


HELMET IMPACT TESTS: ANR EARCUP STRUCTURAL INTEGRITY AND THE EFFECT OF THE ANR EARCUP SYSTEM ON HELMET ENERGY ATTENUATION

Chris E. Perry

CREW SYSTEMS DIRECTORATE BIODYNAMICS AND BIOCOMMUNICATIONS DIVISION WRIGHT-PATTERSON AFB OH 45433-7901



19950111 094

MARCH 1993

DIEG QUALATT HERESONE S

INTERIM REPORT FOR THE PERIOD SEPTEMBER 1992 - DECEMBER 1992

Approved for public release; distribution is unlimited

AIR FORCE MATERIEL COMMAND WRIGHT-PATTERSON AIR FORCE BASE, OHIO 45433

NOTICE

When US Government drawings, specifications, or other data are used for any purpose other than a definitely related Government procurement operation, the Government thereby incurs no responsibility nor any obligation whatsoever, and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise, as in any manner, licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

Please do not request copies of this report from the Armstrong Laboratory. Additional copies may be purchased from:

National Technical Information Service 5285 Port Royal Road Springfield VA 22161

Federal Government agencies and their contractors registered with Defense Technical Information Center should direct requests for copies of this report to:

Defense Technical Information Center Cameron Station Alexandria VA 22314

TECHNICAL REVIEW AND APPROVAL

AL/CF-SR-1993-0006

This report has been reviewed by the Office of Public Affairs (PA) and is releasable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nationals.

This technical report has been reviewed and is approved for publication.

FOR THE COMMANDER

THOMAS J. MOORE, Chief

Biodynamics and Biocommunications Division

Crew Systems Directorate

Thomas of Moore

Armstrong Laboratory

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blan	nk)	2. REPORT DATE		3. REPORT TYPE AND		
<u> </u>		MARCH 1993				992 TO DECEMBER 1992
4. TITLE AND SUBTITLE					5. FUND	ING NUMBERS
HELMET IMPACT TESTS: A	NR I	EARCUP STRUCTURAL	INT	EGRITY AND	PE - 6	52202F
THE EFFECT OF THE ANR				ENERGY	PR - 7	
ATTENUATION						723131
6. AUTHOR(S)	WU - :	72313101				
CHRIS E. PERRY						
7. PERFORMING ORGANIZATION N	IAME(S) AND ADDRESS(ES)			8. PERF	ORMING ORGANIZATION
Armstrong Laboratory,			ate			RT NUMBER
Biodynamics and Biocom						
Human Systems Center		AL/0	CF-SR-1993-0006			
Air Force Materiel Com	mano	i				
Wright-Patterson AFB O						
9. SPONSORING/MONITORING AG			S)			ISORING / MONITORING
		•			AGE	NCY REPORT NUMBER
11. SUPPLEMENTARY NOTES						
12a. DISTRIBUTION / AVAILABILITY	STAT	EMENT			12b. DIS	TRIBUTION CODE
	-	11 . 11 . 1		1 1		
Approved for public r	elea	ase; distribution	1S 1	unlimited.		
13. ABSTRACT (Maximum 200 word						
An experimental effort						
earcup during helmet i						
attenuation properties						
was completed using th	ie Ci	rew Systems Directo	ora	te's Helmet Dr	op Fac	cility in which a
helmeted headform expe	erier	nces a guided free:	fal.	l onto a rigid	steel	l anvil to produce
a dynamic impact at 35						
were compared in helme	et in	npacts using the H	ſĠU−!	53/P and $HGU-5$	5/P he	elmets. The earcups
were equal in their pe						
energy attenuation pro	pert	ties of the helmet	sys	stems. The st	andard	l earcup's
structural integrity w	as i	not compromised du	ring	g the impacts;	howev	ver, the ANR
earcups sustained stru	ıctuı	ral damage to thei:	r o	iter shell and	their	gel filled ear
cushion.						_
						45 MUNADEO OS 01 015
14. SUBJECT TERMS						15. NUMBER OF PAGES
Helmet Impact		Helmet Structural	Int	tegrity		32
Energy Attenuation		ANR Earcup				16. PRICE CODE
AT CECUDITY CLASSICIATION	10 5	COUNTY OF ACCIDICATION	140	SECURITY CLASSIFICA	ATION	20. LIMITATION OF ABSTRACT
17. SECURITY CLASSIFICATION OF REPORT		ECURITY CLASSIFICATION OF THIS PAGE	19.	OF ABSTRACT	AHUN	ZO. LIIVITATION OF ADSTRACT
UNCLASSIFIED		NCLASSIFIED		UNCLASSIFIED		UNLIMITED

THIS PAGE LEFT BLANK INTENTIONALLY

PREFACE

An experimental effort was conducted to measure the structural integrity of the ANR earcup system, and to measure the effects the ANR earcup system would have on the helmet's energy attenuation properties and pilot safety during helmet impact. The tests were conducted for the Life Support Systems Program Office by the Escape and Impact Protection Branch of the Armstrong Laboratory.

Accession For	- mene
NTIS GRAMI DTIC TAB	
Unannownced Justification	
Distribution (iga.
Availability (yeden
Dist Special	

TABLE OF CONTENTS

																						PAGE NO.
INTRODUCTION					•			•														1
METHODS	•	•	•	•	•	•	•			•												2
RESULTS	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	6
CONCLUSIONS	•	•	•	•	•	•	٠	•	•	•	•	•	•	•	•	•	٠	•	•	•	•	25
REFERENCES .	•	•	•	•	•	•	•	•	•	•		•										26

LIST OF FIGURES

FIGURE	PAGE NO.	
1	AL/CFBE Helmet Drop Facility	
2	Headform Acceleration: HGU-2/P in Cell A 7	
3	<pre>Impact Loading: HGU-2/P in Cell A 7</pre>	
4	Headform Acceleration: HGU-2/P in Cell B 8	
5	<pre>Impact Loading: HGU-2/P in Cell B 8</pre>	
6	Headform Acceleration: HGU-2/P in Cell C 9	
7	<pre>Impact Loading: HGU-2/P in Cell C 9</pre>	
8	Headform Acceleration: HGU-55/P in Cell D . 10	
9	Impact Loading: HGU-55/P in Cell D 10	
10	Headform Acceleration: HGU-55/P in Cell E . 11	
11	Impact Loading: HGU-55/P in Cell E 11	
12	Headform Acceleration: HGU-53/P in Cell H . 12	
13	Impact Loading: HGU-53/P in Cell H 12	
14	Headform Acceleration: HGU-53/P in Cell I . 13	
15	Impact Loading: HGU-53/P in Cell I 13	
16	Headform Acceleration: HGU-53/P in Cell J . 14	
17	Impact Loading: HGU-53/P in Cell J 14	
18	Headform Acceleration: HGU-53/P in Cell K . 15	
19	Impact Loading: HGU-53/P in Cell K 15	
20	Structural Test Headform Acceleration Cell L 16	
21	Structural Test Impact Loading: Cell L 16	
22 23	ANR Earcup Damage After Test #4 17 ANR Earcup Damage After Test #5 18	
23 24	ANR Earcup Damage After Test #5	
25	ANR Earcup Damage After Test #7 20	
26	Damage to Gel-Filled Earpap After Test #7	
27	Point of Impact for 50 ft-lb Impact Energy Test 23	
28	Damage to Liner of 53/P Helmet After 50 ft-1b 24	
20	Impact Energy Test	
	impact incly/ lost	
	LIST OF TABLES	
TABLE	PAGE NO.	
1	Holmot/AND Toot Matrix	
1	Helmet/ANR Test Matrix	

THIS PAGE LEFT BLANK INTENTIONALLY

INTRODUCTION

In order to ensure maximum safety and protection for Air Force pilots, any change or addition to standard flight helmets often will necessitate additional helmet testing to ensure compliance with USAF helmet design requirements. For example, modified ANSI Z-90 standard is used to evaluate the structural characteristics (impact energy attenuation, impact penetration resistance) of the HGU-53/P helmet. Any modification to the helmet would potentially require re-evaluation.

Recently, the USAF has been pushing for the addition of the ANR earcup system to the HGU-55/P and HGU-53/P flight helmets. The ANR earcup is a modification to the standard helmet system and therefore it was required to evaluate the following:

- 1) Does the new earcup system affect the helmet's energy attenuation properties?
- 2) Will the ANR system impinge on the pilot's ear region after a side impact on the helmet?
- 3) Will the ANR system structurally withstand a side impact on the helmet?

METHODS

The impact testing (energy attenuation) of the flight helmets in this program was completed using the AL/CFBE Helmet Drop Facility (HDF) located in Bldg 824. The facility, when used for impact testing, is composed of a small, vertical displacement carriage to which a low resonant magnesium alloy headform is mounted. The facility can also be used to test the penetration resistance of helmet shells in which case the headform is rigidly mounted at the base of the carriage. The carriage and helmeted headform are allowed to undergo a guided freefall onto a rigid hemispherical steel anvil 1.9 inches in radius to produce a dynamic impact. Testing was conducted such that the anvil would impart 35 ft-lbs of energy to the helmet at the point of impact. The HDF with the HGU-26/P helmet mounted on the headform is shown in Figure 1.

This test program was conducted using four separate helmets. They were a HGU-2/P, one HGU-55/P, and two HGU-53/P helmets. The HGU-2/P and one of the HGU-53/P helmets were fitted with standard earcups. The remaining helmets were fitted with the ANR system. The test matrix is shown in Table 1.

TABLE 1. HELMET/ANR TEST MATRIX

TEST #	CELL	HELMET	ORIENTATION	EARCUP	DROP HEIGHT
1	A	HGU-2/P	Right Side	Standard	28.4"
2	В	HGU-2/P	Left Side	Standard	28.4"
3	С	HGU-2/P	Right Side	Standard	28.4"
4	D	HGU-55/P(1)	Right Side	ANR	30.29"
5	E	HGU-55/P(1)	Left Side	ANR	30.29"
Deleted	F	HGU-55/P(2)	Right Side	Standard	28" +
Deleted	G	HGU-55/P(2)	Left Side	Standard	28" +
6	Н	HGU-53/P(1)	Right Side	ANR	31.00"
7	I	HGU-53/P(1)	Left Side	ANR	31.00"
8	J	HGU-53/P(2)	Left Side	Standard	32.35"
9	K	HGU-53/P(2)	Right Side	Standard	32.35"
10	L	HGU-53/P(2)	Right/Top	Standard	46.21"

Test cells A, B, and C were pre-test drops used to determine the facility friction factor during guided freefall (the test carriage is guided on steel cables).




FIGURE 1. AL/CFBE HELMET DROP FACILITY

This was found by comparing actual freefall time to the theoretical freefall time. Theoretical freefall was calculated using the following equation:

$$t_{tf} = ((2*h)/a)^{0.5}$$

where t_{tf} is the theoretical freefall, h is the estimated initial drop height (calculated from h = E/w where E is required energy at impact and w is weight of carriage and helmet), and a is the acceleration due to gravity (32.2 ft/s²). Knowing the required initial energy was 35 ft-lbs and the HGU-2/P helmet and carriage weight was w = 14.78 lbs, the initial height was found to be h = 28.42 in, and the corresponding theoretical free fall time was found to be t_{tf} = 0.3957 sec. From these two values, the facility friction factor was found to be f = 0.0305 using the following equation:

$$f = (t_{af} - t_{tf})/t_{tf}$$

Since this value could be affected by temperature and humidity, all tests were completed on the same day the factor was determined. For each test in the matrix, the helmet with liner and earcups were fitted onto the rigid headform such that the area of helmet impact (side over each earcup) was positioned directly over impact anvil. The helmet was secured to the headform by its retention system (nape and chin straps) to prevent movement during freefall. The drop height for each test was determined using the following equation:

$$D_h = [(I_c/w) + f*(I_c/w)]$$

where D_h is the drop height, I_c is the impact energy, w is the total weight at freefall (carriage and helmet), and f is the facility friction factor. The helmet/carriage assembly was raised to the proper height for each test and then the carriage was released from an electronically activated solenoid and allowed to freefall. For tests 1 through 9, the impact energy was 35 ft-lbs as stated before, but for test 10, the energy was increased to 50 ft-lbs to determine the structural integrity of the 53/P helmet to an impact at a point approximately halfway between the earcup and the top. This was done at the request of the Life Support SPO.

Data collection was simple and consisted of: (1) a time trace of the acceleration of the headform using a single axis accelerometer mounted at the approximate center-of-gravity, (2) a time trace of the load imparted to the headform using a flat load cell (10k pound max) mounted under the impact anvil, and (3) the trigger signal used to operate the solenoid release. Test requirements for the data consisted of analyzing the acceleration waveforms and comparing them to the modified ANSI Z-90 helmet

impact standards which state the following: acceleration of the test headform shall not exceed 400 Gs, nor shall it exceed 200 Gs for 3 milliseconds or more, and nor shall it exceed 150 Gs for 6 milliseconds or more. Additional helmet evaluation consisted of observation of the structural integrity of the ANR earcups and comparing them to the standard earcups. All tests were documented using a KODAK high-speed video system running at approximately 500 frames per second.

RESULTS


All test data was collected at 10K samples per second and filtered at 1K Hz. Test cells F and G were not conducted per instructions from Life Support SPO. For each test, a plot was constructed for the acceleration and the load time histories with the time referenced to the start of helmet free-fall. These plots can be found in Figures 2 through 21. From these plots, the peak acceleration, peak load, and Z-90 acceleration time requirements could be obtained. This information is summarized below.


TABLE 2. HELMET IMPACT DATA SUMMARY


	T .				
TEST #	TIME 400 G	OVER G 200 G	(MS) 150 G	PEAK ACCELERATION (G)	PEAK LOAD (LBS)
11	0	0	1.2	173	2205
2	0	0	0.5	161	2080
3	0	0	1.2	193	2467
4	0	0	0	88	1278
5	0	0	0	93	1271
6	0	0	0	117	1457
7	0	0	0	129	1739
8	0	0	0	116	1459
9	0	0	0	112	1381
10	0	0.8	1.2	286	3530


As shown in Table 2, the energy attenuation properties of the helmet systems with both the standard and ANR earcups satisfied the Z-90 criteria with little problem. Even the last test at a 50 ft-lb impact energy using the HGU-53/P helmet and standard earcup had no problem meeting the criteria.


The structural integrity of the ANR earcup system can be demonstrated in Figures 22 through 26. The figures document that in the HGU-55/P helmet, the earcups show little deformation after impact other than slight cracks on the back of each earcup shell as shown by Figures 22 and 23. Figures 24 and 26 show that in the HGU-53/P helmet, the ANR shell received major structural damage after impact. Figure 25 also shows where the gel filled earpad ruptured after impact. The standard earcups in either the 55/P or 53/P helmet did not sustain structural damage (shell or earpad) after impact.




















































HELMET STRUCTURAL TEST AT IMPACT ENERGY=50 FT-LB



HELMET STRUCTURAL TEST AT IMPACT ENERGY=50 FT-LB








FIGURE 23. ANR EARCUP DAMAGE AFTER TEST #5




FIGURE 24. ANR EARCUP DAMAGE AFTER TEST #6




FIGURE 25. ANR EARCUP DAMAGE AFTER TEST #7




FIGURE 26. DAMAGE TO GEL-FILLED EARPAP AFTER TEST #7

Figure 27 shows the point of impact for the final test conducted at the 50 ft-lb impact energy level. The HGU-53/P helmet showed no visible damage to the outer shell, but the inner styrofoam liner beneath the point of impact was damaged as shown in Figure 28. This is the function of the liner (energy absorption) and was considered a positive test result.



FIGURE 27. POINT OF IMPACT FOR 50 FT-LB IMPACT ENERGY TEST




FIGURE 28. DAMAGE TO LINER OF 53/P HELMET AFTER 50 FT-LB IMPACT ENERGY TEST

CONCLUSIONS

Tests were conducted on a helmet drop facility to compare standard earcups and the ANR earcups in two areas: effect on helmet impact energy attenuation, and earcup structural integrity. The earcups performed equally well in their ability to affect the energy attenuation properties of the helmet system when subjected to an impact of 35 ft-lbs. The standard earcup's structural integrity was much better than the ANR earcups as the standard earcups displayed no damage during impact, but each ANR earcup sustained some damage to its outer shell during impact. A possible explanation for this could be that the standard earcup has a low density foam cushion that forms to the ear, while the ANR earcup has a high density gel cushion that would not absorb the short-time duration energy from the impact as well as the low density foam. The results would be that the energy transmitted through the helmet shell during impact would be partially absorbed by the outer shell of the ANR earcup instead of the cushion, resulting in structural failure of the earcup shell.

REFERENCES

- Brinkley, J.W. Review of Operational Efficacy of USAF Flight Helmets in Crash and Escape Environments. AMRL-TR-75-74, August 1975.
- 2. Critical Item Development Specification DS-001. Aeronautical Systems Division, USAF, 12 June 1989.
- 3. Interim-Night Integrated Goggle and Head Tracking System Safety of Flight Requirements. Personal Protective Systems Branch, Naval Air Development Center, August 1989.
- 4. Rayne, J.M. and Maslen, K.R. Factors in the Design of Protective Helmets. Aerospace Medicine 40 6:631-637, 1969.